

KeyLab Firmware 1.33 (49/61) 1.19(25) Release Note

Installation

Version number check and upgrade should be done with Unified MIDI Control Center.

New Features

- Pad backlighting can be activated using MIDI note messages on channel 10 (if you play back a track recorded using pads, with KeyLab as MIDI destination, pad's LEDs show what have been played).
- Compatible with future Analog Lab upgrade (allowing better integration)

Bug Fixes (since 1.29/1.16)

- Proper handling of Bank 1/Bank 2 (several fixes).
- Fader may erroneously send two messages on separate MIDI channel for each move (fixed)
- Settings done using MIDI Control Center could affect another control than the one edited (fixed)
- No messages sent by knob when set in RPN/NRPN mode **and** control number MSB is equal to control number LSB (fixed).

Known Problems

- Regarding pad backlighting feature, if several note messages are sent close together, some of them may be ignored (and the corresponding pad won't light up).